

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2019

Submitted Date:

08/22/2019

Document Number:

688305614**FIELD INSPECTION FORM**
 Loc ID 317256 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 69760Name of Operator: PETRON DEVELOPMENT COMPANYAddress: 1899 W LITTLETON BLVDCity: LITTLETON State: CO Zip: 80120**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Walker, Jimmy	(303) 794-5300	jim@petron.net	
Young, Rob		rob.young@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237494	WELL	PR	11/01/2017	OW	121-09997	STENNETT 4-15	PR

General Comment:

Straw bales were inspection on NE cor of east pit (see attached photo).

Gunbarrel at tank battery was being maintained at time of inspection to prevent the backup to crude oil tanks that casue tanks to overtop and <2 bbls went into containment. Stained soil will be removed and properly disposed of per Rule 907e and tanks cleaned within 30 days.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
PW/CO	Tank	<= 1 bbl		
Comment:	Tanks over topped due to gunbarrel malfunction. Liquids stayed inside berm and operator was cleaning up area at time of inspection. Not a reportable spill.			
Corrective Action:	For localized spotting of oily waste - Properly treat or dispose of oily waste in accordance with 907.e.			Date: 09/23/2019

In Containment: Yes ☐Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 237494 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: No COAs.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 237494 Type: WELL API Number: 121-09997 Status: PR Insp. Status: PR**Producing Well**Comment: [Jun 2019 production reported to COGCC database.](#)

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688305622	Petron Stennett 4-15 straw bales on NE cor of pits	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917348
688305623	Petron Stennett 4-15 tank containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917349
688305624	Petron Stennett 4-15 gunbarrel and tanks	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4917350