

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402352695

Date Received:
03/26/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Spence Laird

405-420-8415

slaird@sandridgeenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689803758

Inspection Date: 03/05/2020

FIR Submit Date: 03/10/2020

FIR Status: _____

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC

Company Number: 10598

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 436007

Location Name: Grizzly Number: 3-32H County: _____

Qtrqr: NENW Sec: 32 Twp: 8N Range: 80W Meridian: 6

Latitude: 40.627697 Longitude: -106.397825

FACILITY - API Number: 05-057-00 Facility ID: 436007

Facility Name: Grizzly Number: 3-32H

Qtrqr: NENW Sec: 32 Twp: 8N Range: 80W Meridian: 6

Latitude: 40.627697 Longitude: -106.397825

CORRECTIVE ACTIONS:

1 CA# 137309

Corrective Action: Comply with Rule 603.f .

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 03/26/2020

Operator
Comment:

Per phone conversation on 3/26/20 between Emily Waldron, COGCC, and Spence Laird, Sandridge, it has been discussed and agreed upon to leave the pumping unit on location on the bases of the pumping unit is needed for long-term production of the well. This pumping unit was on location to produce the well until operator restimulated well in late 2019 which then created an uptick in fluid production calling for an esp to be used to produce the well correctly. This well should decline in the upcoming months and the esp will be pulled and the pumping unit will then be used again to produce the well.

COGCC Decision: _____

COGCC
Representative:

| |
|--|
| |
|--|

OPERATOR COMMENT AND SUBMITTAL

Comment: Per phone conversation on 3/26/20 between Emily Waldron, COGCC, and Spence Laird, Sandridge, it has been discussed and agreed upon to leave the pumping unit on location on the bases of the pumping unit is needed for long-term production of the well. This pumping unit was on location to produce the well until operator restimulated well in late 2019 which then created an uptick in fluid production calling for an esp to be used to produce the well correctly. This well should decline in the upcoming months and the esp will be pulled and the pumping unit will then be used again to produce the well.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Spence Laird

Signed: _____

Title: EHSR

Date: 3/26/2020 9:37:18 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
|-------------------------------|---------------------------|

| | |
|--|--|
| | |
|--|--|

Total Attach: 0 Files