

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2020

Submitted Date:

04/09/2020

Document Number:

693502649

FIELD INSPECTION FORM

Loc ID 333292 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
	303-825-4822	cogcc@kpk.com	All inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240697	WELL	PR	02/16/1976	OW	123-08485	LAWRENCE TOTEMS 2	SI

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 05/09/2020

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Plunger Lift	#		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 240697 Type: WELL API Number: 123-08485 Status: PR Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI At time of inspection flowline valves off well head appear to be in the closed position.Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday April 9, 2020 at approximately 8:05AM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Lawrence Totems #2 Operator: KP Kauffman API#:05-123-08485 County: Weld While there, I observed Well site During this inspection the following possible compliance issues were observed: Sign condition: Rule 210 e Corrective action date of 5-9-20 Weather conditions: sunny and site dry. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	04/09/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402366670	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5119472
693502650	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5119462