

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

697001116**FIELD INSPECTION FORM**Loc ID 429567 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	
,		cogccinspections@srcenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443914	TANK BATTERY	AC	11/10/2015		-	Loeffler K/1-69-1HN tank battery	AO

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	VRT's lack placards. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	06/30/2020
Type	CONTAINERS		
Comment:	Methanol and chemical systems		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Concrete vault at north side of compressor lacks all placards. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	06/30/2020
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Soundwall at compressor		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 12		

Comment:	Pilots are on		Date:	
Corrective Action:			Date:	
Type: VRT	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Prime Mover	# 2			
Comment:	Natural gas engines on compressor and VRU.		Date:	
Corrective Action:			Date:	
Type: Vertical Separator	# 3			
Comment:			Date:	
Corrective Action:			Date:	
Type: VRU	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pig Station	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 4			
Comment:	Calibration cards are current.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	#			
Comment:	Automation arrays, solar arrays, electrical systems, ECD scrubbers, lube oil storage in secondary containment with wildlife netting, antifreeze storage in secondary containment with wildlife netting, methanol and chemical storage in secondary containment with wildlife netting, methanol and chemical systems in secondary containment.		Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 10			
Comment:	Separators are anchored.		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		40.342750,-104.731530
Comment:	60 bbls at VRU				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Peterson, Tom

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	BV CONCRETE		40.342660,-104.732190
Comment:	12 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<100 BBLs	BV CONCRETE		40.344430,-104.731720
Comment:	At compressor. Unknown contents/capacity.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	No berm has been constructed. See attached photo.				
Corrective Action:	Install berms or other secondary containment devices per Rule 906.d.(1).				Date: 06/30/2020

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.342740,-104.731510
Comment:	Maintenance tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLs	BV CONCRETE		,
Comment:	60 bbls				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	500 BBLs	STEEL AST		,
Comment:	Produced water tanks are anchored.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	500 BBLs	STEEL AST		40.343030,-104.731810
Comment:	Crude oil tanks are anchored.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402382098	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133724
697001117	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133718