

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402389064

Date Received:
05/04/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102498
Inspection Date: 03/31/2020 FIR Submit Date: 03/31/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308800

Location Name: APACHE CANYON-634S67W Number: 7SWNW County: LAS ANIMAS
Qtrqtr: SWN Sec: 7 Twp: 34S Range: 67W Meridian: 6
W
Latitude: 37.099561 Longitude: -104.936796

FACILITY - API Number: 05-071- -00 Facility ID: 282124

Facility Name: APACHE CANYON Number: 7-5
Qtrqtr: SWN Sec: 7 Twp: 34S Range: 67W Meridian: 6
W
Latitude: 37.099561 Longitude: -104.936796

CORRECTIVE ACTION:

1 CA# 137638

Corrective Action: COMPLY WITH NTO AND RULE 603.f.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator Comment: The riser is an active low point drain. The riser was labeled as such for clarity. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 137639

Corrective Action: COMPLY WITH RULE 603.f.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator Comment: The piece of equipment that the inspector found on the ground is the belt guard to the pumping unit. The guard was removed to service the clutch. The belt guard was placed back over the belts, this equipment is in use.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 137640

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator Comment: The fluid accumulation in the liquid ring containment was removed and the skid was cleaned. Maintenance was conducted to stop the leak. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 5/4/2020 3:15:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402389108	Photo Log
-----------	-----------

Total Attach: 1 Files