

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/11/2020

Submitted Date:

05/12/2020

Document Number:

700401431

FIELD INSPECTION FORMLoc ID 316192 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256078	WELL	TA	04/01/2001	GW	103-09976	PARKER 4-35	TA

General Comment:

On 4-9-2020 at approximately 15:00, inspector Rick Moran, conducted a follow up inspection at 31 Operating well Parker 4-35 in Rio Blanco county FIR documents:

- 1) 700400888 dated 4-6-2020.
- 2) 700400944 dated 4-9-2020.
- 3) 699700122 dated 4-9-2020.

The following compliance issues were resolved:

- 1) Well sign phone number was corrected.
- 2) Lease road culvert was replaced.

The following compliance issues are uncompleted:

- 1) Submit eForm 27 in reference to the pit closure. Photo 3. Complete by 6-15-2020.
- 2) Removal of impacted soil from spill around well head. Photo 2. Complete by 5-15-2020.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700401431.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		
Crude Oil				
Comment:	COGCC staff observed "Oil gator" (Doc #402370256) covering the staining around the wellhead but the impacted material has not been removed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.			Date: <u>05/15/2020</u>

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 256078 Type: WELL API Number: 103-09976 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last recorded production January 2002. Last MIT on 4-5-2017.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Drilling PitLined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____

Fencing Condition: _____

Comment: No fence present.

Corrective Action

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____

Oil Accumulation: NO2+ feet Freeboard: YESComment: COGCC staff observed an earthen pit located approximately 60 feet northwest of the wellhead.

Corrective Action

Operator shall submit an eForm 27 Site Investigation and Remediation Workplan to close the pit on location.Date: 06/15/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402395624	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5147530
700401432	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5147525