

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402492720

Date Received:

09/18/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902118

Inspection Date: 08/11/2020

FIR Submit Date: 08/12/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325820

Location Name: HUBER-BURKETT-N35N8W Number: 25SENW County: LA PLATA

Qtrqtr: SENW Sec: 25 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276300 Longitude: -107.699500

FACILITY - API Number: 05-067-00 Facility ID: 215426

Facility Name: HUBER-BURKETT Number: 1-25

Qtrqtr: SENW Sec: 25 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276300 Longitude: -107.699500

CORRECTIVE ACTIONS:

1 CA# 141189

Corrective Action: Cut and bag flowering musk thistles to prevent seed dispersal and control weeds.

Date: 08/28/2020

Response: CA COMPLETED

Date of Completion: 09/17/2020

Operator Comment: Musk thistle removed

COGCC Decision: _____

--

Date: 9/18/2020 10:26:32 AM

Total Attach: 1 Files