

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2020

Submitted Date:

09/14/2020

Document Number:

698701895

FIELD INSPECTION FORM

Loc ID 309257 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergyllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290788	WELL	PR	07/01/2011	GW	071-09302	HILL RANCH 25-7	PR

General Comment:

This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c. Operator is prohibited from placing non Exploration and Production Waste in produced water tanks.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Meter house sign adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:

Type	OTHER		
Comment:	For localized stained soils or oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."		
Corrective Action:	907.e."	Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	#			corrective date
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:	30 bbl pit tank				
Corrective Action:				Date:	

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	

Venting:

Yes/No				
Comment:				
Corrective Action:			Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 290788 Type: WELL API Number: 071-09302 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (9/14/2020) at approximately at (12:30 HRS), I, Inspector (Abe Serna), Conducted an on-site inspection at (Hill Ranch #25-7) (Orgis Operating), at (Location #309257) in (Las Animas County) Colorado. While there, I observed a (PR Well) During this inspection compliance issues were observed. For localized stained soils or oily waste - "Properly treat or dispose of oily waste in accordance with 907.e." A follow up on this site inspection needs to be conducted. This is a summary of inspection report.</p>	sernaa	09/14/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402488929	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246919
698701896	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246913