

Location

Lease Road:			
Type	Access		
comment:	well is in a planted field		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate, form 10 Doc # 402476685 was submitted on 9-30-20 and is in process, should be updated to reflect current operator.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Bradenhead	# 1			
Comment:	appears to be plumbed to surface			
Corrective Action:		Date:		
Type: Ancillary equipment	# 1			
Comment:	automation			
Corrective Action:		Date:		

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241320 Type: WELL API Number: 123-09109 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: test date is over 1 year

12/18/2020

Corrective Action: Comply with rule 206

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On wednesday 11/18/2020 at approximately 1415 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman/Peterson Energy Operating Inc.location: Rasmussen 2 at API #05-123-09109 in Weld County Colorado. While there, I observed wellsite, Form 10 Doc # 402476685 was submitted on 9-30-20 and is in process.This inspection is for this wellsite only, TB was inspected with Doc # 699302567. During this inspection the following possible compliance issues were observed: 206 reporting: Bradenhead test is over 1 year old. CA date 12/18/2020. See attached photos. Location: dry, Weather: clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	11/18/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302992	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293854