

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

11/23/2020

Document Number:

693802531**FIELD INSPECTION FORM**Loc ID 322096 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**OGCC Operator Number: 10754Name of Operator: FOUR CORNERS ENERGY LLCAddress: 531 E 770 NCity: OREM State: UT Zip: 84097**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Williams, Larry	(801) 657-5780	larry@thesummitcompanies.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208958	WELL	SI	01/01/2017	GW	033-06063	SANTA FE CANYON-FEDERAL 42-18	SI

General Comment:

COGCC staff performed a followup field inspection on 11/19/2020. Followup to inspection doc#693802465 on 10/01/2020. Issues were found requiring corrective action. CA(s) from previous inspection not completed. See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
Lease Road:			
Type	Main		
comment:			
Corrective Action		Date:	
Type	Access		
comment:			
Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Framed metal sign at SW corner of tank berms. CA Completed.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels applied. CA completed		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	801-657-5780 or 435-279-7144. CA completed		
Corrective Action:		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	No audible leak at wellhead. CA completed.		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Weeds removed. CA completed.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Flow Line	#		corrective date
Comment:	Multiple on/off location flowlines. No Form 44 on record. CA date remains as previously noted.		
Corrective Action:	Submit an eForm 44 Flowline Report per Rule 1101.a.		Date: 11/06/2020
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	#	
Comment:	Bradenhead plumbed to surface. CA completed.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		37.641994,-108.980477
Comment:	Tank over 1/2 full of oil/water. Inlet flowline with broken elbow. CA date remains the same from previous inspection.				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d				Date: 10/23/2020

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		37.642452,-108.980042
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 208958 Type: WELL API Number: 033-06063 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well shut in 11/2016. No MIT on record.
Well was found in state of Temporary Abandonment. Well TA longer than 6 months with no Form 4 submitted
Well is overdue for Mechanical Integrity Test (MIT). MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.
Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b

Corrective Action: Submit Form 4 as directed by Rule 319.b
Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 11/04/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402538541	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5296472
693802544	Inspection photos 11/19/2020	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5296458