

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2020

Submitted Date:

12/30/2020

Document Number:

699502097**FIELD INSPECTION FORM**Loc ID 329482 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249615	WELL	PR	03/01/2020	GW	123-17418	LAURIDSON VV 18-10	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Fencing needs to be fixed. Wellhead sign is not visible upside down on ground.

Corrective Action: Comply with 603 f

Date: 01/09/2021

Equipment:

corrective date

Type: Ancillary equipment

1

Comment: Automation

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 249615 Type: WELL API Number: 123-17418 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: Will need new bradenhead test soon.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 12/30/20 at approximately 1240 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Lauridson VV 18-4J</p> <p>Company Name- KPK</p> <p>API- 05-123-17406</p> <p>In Weld County Colorado.</p> <p>While there, I observed producing well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Fencing needs to be fixed. Wellhead sign is not visible upside down on ground.</p> <p>Comply with 603 f 1/9/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection weather conditions were cold, calm, recent snow.</p> <p>This is a summary of inspection report.</p>	medinaj	12/30/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402563775	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318990
699502098	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318985