

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds inside wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 603.f.		Date: 04/12/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	iron		
Corrective Action:			Date:

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 251376 Type: WELL API Number: 123-19179 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: sunny, snow on ground On Tuesday, January 12, 2021 at approximately 16:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at HSR-VETTER 12-36 (PDC Energy), at location #: 330485 in WEOLD COUNTY Colorado. While there, I observed a producing wellhead. During this inspection the following possible compliance issues were observed: 1. Weeds inside wellhead fencing. Remove to comply with Rule 603.f. (Corrective Action Date: April 12, 2021) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	01/12/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402573192	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328276
679603619	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328274