

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Type: Bradenhead		# 1		
Comment:	Bradenhead valve is exposed at surface.			
Corrective Action:			Date:	
Type: Bird Protectors		# 1		
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run		# 1		
Comment:				
Corrective Action:			Date:	
Type: Flow Line		# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Secondary containment is inadequate to contain largest single tank plus sufficient freeboard.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.			Date: 03/05/2021

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 216840 Type: WELL API Number: 069-06027 Status: PR Insp. Status: SI

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/09/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 2/2/2021 at approximately 11:30 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Magpie Operating Minch 1X location #307092 in Larimer County, Colorado. While there, I observed the crude oil tank berm was insufficient. During this inspection the following possible compliance issues were observed: Rule 603. with a corrective action date of 3/5/2021. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	02/02/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402589482	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342993
697002971	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342982