

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2021

Submitted Date:

02/18/2021

Document Number:

695103994**FIELD INSPECTION FORM**Loc ID 309159 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289003	WELL	PR	01/10/2008	GW	071-09179	CHRISTINE FEDERAL 23-19	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Phone 3: SEVERAL AREAS OF IMPACTED SOIL APPEARS TO BE OIL CONTAMINATION FROM COMPRESSOR FLUIDS. Phone 4: AREA OF IMPACTED SOIL OUTSIDE OF METER HOUSE APPEARS TO BE OILY WASTE FROM SEPARATOR.		
Corrective Action:	COMPLY WITH RULE 906. COMPLY WITH 901.b IN HANDLING SOLID WASTE MATERIAL (i.e.. IMPACTED SOIL).		Date: <u>03/08/2021</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Prime Mover	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Phone 5: DRIP APPROX. 50 YARDS WEST OF CHRISTINE FEDERAL APPEARS TO HAVE BEEN DRAINED ON GROUND, THERE IS AN AREA OF IMPACTED SOIL APPEARING TO HAVE OIL CONTAMINATION ON GROUND AND IN THE SNOW. Phone 6: APPEARS THAT DRIP HAS BEEN DRAINED ON THE GROUND AFTER ORIGINAL DATE OF INSPECTION. Phone 7: ANOTHER IMAGE OF WHAT APPEARS TO BE OILY WASTE DRAINED FROM DRIP.		
Corrective Action:	COMPLY WITH RULE 906. DO NOT DRAIN ANY E&P OR NON E&P WASTE ON THE GROUND. COMPLY WITH 901.b IN HANDLING SOLID WASTE MATERIAL (i.e.. IMPACTED SOIL).		Date: <u>03/10/2021</u>
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:	4"		
Corrective Action:			Date:
Type: Compressor	# 1		

Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	ALL HAVE MARKERS		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Other	# 4		
Comment:	SOUND WALLS AROUND PRIME MOVER		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 289003	Type: WELL	API Number: 071-09179	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Drains	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
INSPECTION DUE TO COMPLAINT #200449363, Phone 8: POSITION OF SOUND METER DURING SOUND STUDY. CALCULATED db DURING SOUND STUDY IS 39.56 db.	beardslt	02/08/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402602672	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354660">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354660</a>
695103995	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354655">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354655</a>
695104003	SOUND STUDY	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354656">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354656</a>