

Location			
Lease Road:			
Type	Access		
comment:	in crop		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	one well head displays a different operator name. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 07/19/2021
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	iron		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 295921 Type: WELL API Number: 123-25860 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: TANK BATTERY CONNECTED

Comment:

Corrective Action: Date:

Facility ID: 419712 Type: WELL API Number: 123-32326 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: TANK BATTERY CONNECTED

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: cloudy, dry ground On Monday, April 19, 2021 at approximately 10:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at LEFFLER SE-2 (PDC Energy), at location #:310076 in WELD COUNTY Colorado. While there, I observed shut in wellheads. During this inspection the following possible compliance issues were observed: 1. One wellhead displays previous operator name. Install sign to comply with Rule 605.d. (Corrective Actions Date: July 19, 2021) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	04/19/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402665275	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408563
679603809	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408550