

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402723294

Date Received:
06/18/2021

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

0 CA Completed
6 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

tyson.johnston@oxbow.com

heather.lang@oxbow.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202820

Inspection Date: 06/15/2021

FIR Submit Date: 06/16/2021

FIR Status: _____

Inspected Operator Information:

Company Name: GUNNISON ENERGY LLC

Company Number: 10515

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 453805

Location Name: Trail Gulch Unit 1090 Number: 30 County: _____

Qtrqtr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.157036 Longitude: -107.477597

FACILITY - API Number: 05-051-00 Facility ID: 453805

Facility Name: Trail Gulch Unit 1090 Number: 30

Qtrqtr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.157036 Longitude: -107.477597

CORRECTIVE ACTIONS:

1 CA# 151933

Corrective Action: Comply with Rule 1002.f and install BMPs to protect/stabilize slopes, and to manage runoff and allow for sediment laden-free stormwater discharge.

Date: 06/18/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Gunnison Energy received inspection #696202820 and discussed the requested corrective actions with the landowner, the United States Forest Service - Grand Mesa Uncompahgre and Gunnison National Forest (USFS-GMUG). Gunnison

Energy respectfully requests additional time to comply with the inspection requirements due to the fact that USFS-GMUG as the landowner does not agree with certain elements in the COGCC inspection requests and would like to schedule an onsite meeting with the COGCC, USFS-GMUG, and Operator to review compliance items and develop mutually agreeable best management practices.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 151934

Corrective Action: Comply with Rule 1002.f and Form 2A permit conditions; take active measures to prevent fugitive dust emissions from the well pad, well pad access entrance, other connecting dirt roads during re-construction, drilling, completion, and production operations.

Date: 06/15/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

Operator Comment: This corrective action is for the same day. This does not allow adequate time to reach cellular signal, call to arrange dust mitigation, and mobilize mitigation measures to the field.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 151935

Corrective Action: Comply with Rule 1002.f and install BMPs to manage runoff and allow for sediment laden-free stormwater discharge.

Date: 06/20/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Gunnison Energy received inspection #696202820 and discussed the requested corrective actions with the landowner, the United States Forest Service - Grand Mesa Uncompahgre and Gunnison National Forest (USFS-GMUG). Gunnison Energy respectfully requests additional time to comply with the inspection requirements due to the fact that USFS-GMUG as the landowner does not agree with certain elements in the COGCC inspection requests and would like to schedule an onsite meeting with the COGCC, USFS-GMUG, and Operator to review compliance items and develop mutually agreeable best management practices.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 151936

Corrective Action: This corrective action has not been addressed and remains applicable; Comply with Rule 1002.f and Rule 1002.c.

Date: 05/24/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Gunnison Energy received inspection #696202820 and discussed the requested corrective actions with the landowner, the United States Forest Service - Grand Mesa Uncompahgre and Gunnison National Forest (USFS-GMUG). Gunnison Energy respectfully requests additional time to comply with the inspection requirements due to the fact that USFS-GMUG as the landowner does not agree with certain elements in the COGCC inspection requests and would like to schedule an onsite meeting with the COGCC, USFS-GMUG, and Operator to review compliance items and develop mutually agreeable best management practices.

management practices.

COGCC Decision: _____

COGCC Representative: _____

5 CA# 151937

Corrective Action: Comply with Rule 1002.f and install BMPs to protect and stabilize the cut and fill slopes of the Location.

Date: 06/18/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Gunnison Energy received inspection #696202820 and discussed the requested corrective actions with the landowner, the United States Forest Service - Grand Mesa Uncompahgre and Gunnison National Forest (USFS-GMUG). Gunnison Energy respectfully requests additional time to comply with the inspection requirements due to the fact that USFS-GMUG as the landowner does not agree with certain elements in the COGCC inspection requests and would like to schedule an onsite meeting with the COGCC, USFS-GMUG, and Operator to review compliance items and develop mutually agreeable best management practices.

COGCC Decision: _____

COGCC Representative: _____

6 CA# 151938

Corrective Action: This corrective action has not been addressed and remains applicable; Comply with Rule 1002.f.

Date: 05/24/2021

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Gunnison Energy received inspection #696202820 and discussed the requested corrective actions with the landowner, the United States Forest Service - Grand Mesa Uncompahgre and Gunnison National Forest (USFS-GMUG). Gunnison Energy respectfully requests additional time to comply with the inspection requirements due to the fact that USFS-GMUG as the landowner does not agree with certain elements in the COGCC inspection requests and would like to schedule an onsite meeting with the COGCC, USFS-GMUG, and Operator to review compliance items and develop mutually agreeable best management practices.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Gunnison Energy has reviewed the requested corrective actions with the surface owner, the United States Forest Service - Grand Mesa Uncompahgre and Gunnison National Forest (USFS-GMUG). USFS-GMUG as the landowner does not agree with certain elements in the COGCC inspection requests and would like to schedule an onsite meeting with the COGCC, USFS-GMUG, and Operator to review compliance items and develop mutually agreeable best management practices.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Donahue

Signed: _____

Title: Compliance Specialist

Date: 6/18/2021 1:27:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files