

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2021

Submitted Date:

07/29/2021

Document Number:

689806093

## FIELD INSPECTION FORM

 Loc ID 313026 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 3975  
 Name of Operator: ARGALI EXPLORATION COMPANY  
 Address: PO BOX 416  
 City: RANGELY State: CO Zip: 81648
**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
General, Contact		argaliexplorationcompany@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223384	WELL	SI	01/01/2020	GW	081-06748	GRYNBERG STATE 3-36	SI

**General Comment:**

Routine FIU inspection. Form 9 to transfer from Mustang to Argali approved 10/6/2020 document number 402424253. Compliance issues observed:

signs not updated to current operator

no bradenhead access apparent

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign knocked over. Sign inaccurate.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	08/30/2021

Emergency Contact Number:

Comment:	No emergency contact for current operator.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	08/30/2021

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:	#		corrective date
Bird Protectors			
Comment:			
Corrective Action:		Date:	
Bradenhead			
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	08/09/2021
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 223384 Type: WELL API Number: 081-06748 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402763876	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5492276">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5492276</a>
689806094	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5492271">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5492271</a>