

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2021

Submitted Date:

08/17/2021

Document Number:

693505453

FIELD INSPECTION FORMLoc ID 323149 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244829	WELL	PR	01/01/2020	GW	123-12624	CHAMPLIN 86 AMOCO F 7	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds on location.		
Corrective Action:	Comply with rule 606	Date:	09/17/2021
Type	OTHER		
Comment:	Stained soil on 2" piping to Hoz Separator.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	09/17/2021
Type	TRASH		
Comment:	Trash black tarp on site		
Corrective Action:	Comply with rule 606	Date:	09/17/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment: PU and associated equipment, 1" piping and parts.		
Corrective Action:	Comply with rule 606	Date:	09/17/2021
Type	OTHER		
Comment:	Mechanical issue: 2" piping to Hoz Separator appears to be leaking.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	09/17/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Square tubing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 244829 Type: WELL API Number: 123-12624 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/10/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday August 17, 2021 at approximately 12:54PM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Champlin 86 Amoco F #7</p> <p>Operator: KP Kauffman</p> <p>API#: 123-12624</p> <p>County: Weld</p> <p>While there, I observed a Producing well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment: Rule 606 Corrective action date of 9-17-21</p> <p>Weeds: Rule 606 Corrective action date of 9-17-21</p> <p>Trash: Rule 606 Corrective action date of 9-17-21</p> <p>Stained soil: Rule 905 e Corrective action date of 9-17-21</p> <p>Mechanical issue: Rule 608 e Corrective action date of 9-17-21</p> <p>It does not appear that KP Kauffman has applied for a variance to store unused equipment on site.</p> <p>Weather conditions: Dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	08/17/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402783248	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5508479
693505454	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5508473