

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2021

Submitted Date:

10/19/2021

Document Number:

693505624

FIELD INSPECTION FORMLoc ID 329482 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249615	WELL	PR	03/01/2020	GW	123-17418	LAURIDSON VV 18-10	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s)		
Corrective Action:	Sign not posted or information inaccurate at well(s)	Date:	11/19/2021

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Unused equipment: chainlink fencing on ground.		
Corrective Action:	Comply with rule 606	Date:	01/09/2021

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 249615 Type: WELL API Number: 123-17418 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/14/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday October 19, 2021 at approximately 10:11AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Lauridson VV #18-10</p> <p>Operator: KP Kauffman</p> <p>API#:123-17418</p> <p>County: Weld</p> <p>While there, I observed producing well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Sign: Rule 605 d Corrective action date of 11-19-21</p> <p>Unused equipment: Rule 606 Corrective action date of 1-9-21</p> <p>Weather conditions: Cloudy</p> <p>This is a follow up inspection per doc#'s 699502097 and 699503047. At time of inspection corrective actions appear to have not been addressed.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	10/19/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402846297	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558591
693505625	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558586