



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241195 Type: WELL API Number: 123-08983 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/22/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Fail			

Comment: [Tracking pad not installed or installed improperly or not adequately maintained to prevent track of material offsite](#)

Corrective Action: [Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.\(2\)F. Additionally, if material is tracked onto county or public roads, contact the appropriate authority.](#)

Date: 05/04/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">COGCC Inspection Report Summary On Tuesday October 19, 2021 at approximately 11:47AM, I, Inspector Randy Silver, Conducted an on-site re-inspection per doc #'s 693505350 and 693505025. Location: UPRR 43 Pan AM I #13 Operator: KP Kauffman API#:05-123-08983 County: Weld While there, I observed a producing well site. During this inspection the following possible compliance issues were observed: Tracking pad: Rule 1002 f (2) f Corrective action date of 05-04-21 See photo's At time of inspection it did not appears any work had been performed to the tracking pad. Weather conditions: Cloudy and dry. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</a>	silverr	10/19/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402846300	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558593">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558593</a>
693505631	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558589">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558589</a>