

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2021

Submitted Date:

11/08/2021

Document Number:

693505772**FIELD INSPECTION FORM**
 Loc ID 319888 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments2 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201790	WELL	PR	04/08/2019	OW	001-07194	COMMUNITY 1	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date:
Corrective Action:			

Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead vegetation along road and on location.		
Corrective Action:	Comply with rule 606	Date:	11/15/2021

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Chain link		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4	
Comment:	Guy line anchors not Properly marked.	
Corrective Action:	Install proper guy line markers per Rule 1003.a. All guy line anchors left buried for future use shall be identified by a marker of bright color not less than four (4) feet in height and not greater than one (1) foot east of the guy line anchor. In addition, all well sites and surface production facilities shall be maintained in accordance with Rule 603.j.	Date: 11/15/2021
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Gas Powered motor	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		-39.927010,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	286bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 201790 Type: WELL API Number: 001-07194 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/08/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday November 8, 2021 at approximately 10:11AM, I, Inspector Randy Silver, conducted an on-site inspection. Location: community 1 Operator: KP Kauffman API#: 001-07194 County: Adams While there, I observed a producing well site and production facility. During this inspection the following possible compliance issues were observed: Debris: Rule 606 corrective action date of 11-15-21 See photos 1,3,5 Guyline anchors: Rule 1003 a Corrective action date of 11-15-21 See photos 3,5 Weather conditions: Cloudy and dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.,</p>	silverr	11/08/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402864662	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5574806
693505773	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5574796