

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/17/2021

Submitted Date:

12/01/2021

Document Number:

689806652

FIELD INSPECTION FORM

Loc ID 312880 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 3975
Name of Operator: ARGALI EXPLORATION COMPANY
Address: PO BOX 416
City: RANGELY State: CO Zip: 81648

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
General, Contact		argaliexplorationcompany@gmail.com	
		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222717	WELL	SI	01/01/2020	GW	081-06077	FEDERAL-BLUE GRAVEL 1-23	SI

General Comment:

Routine FIU follow up inspection. Follow up to inspection from 8/10/2021 document number 689806213. Signs updated.
Compliance issues remaining in this inspection:
no bradenhead access apparent
dried annual weeds
animal burrows in berm
holes in tank

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Annual weeds have dried and become debris.		
Corrective Action:	Comply with Rule 606.	Date:	09/20/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:		#		corrective date
Bradenhead				
Comment:	Bradenhead inaccessible or not visible.			
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)			Date: 08/30/2021
Gas Meter Run		# 1		
Comment:				
Corrective Action:				Date:
Bird Protectors		#		
Comment:				
Corrective Action:				Date:
Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		

Comment: [Holes in tank.](#)

Corrective Action: [Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.](#)

Date: 01/05/2022

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			Inadequate

Comment: [Animal burrows compromising berm.](#)

Corrective Action: [Repair or install berms or other secondary containment devices per Rule 912.d.\(1\).](#)

Date: 09/09/2021

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 222717 Type: WELL API Number: 081-06077 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402884106	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5593524
689806653	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5593514