

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2022

Submitted Date:

01/10/2022

Document Number:

699503437**FIELD INSPECTION FORM**Loc ID 317738 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239892	WELL	PR	12/14/2015	GW	123-07680	FERN MILLER WIKSTRAND 2	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Missing wellhead bolts were observed during inspection with signs of mechanical issues at time of inspection. Mechanical integrity of well may need to be tested to ensure mechanical integrity of wellbore, and wellhead equipment. Contact COGCC engineering. See pictures 2

Corrective Action:

Comply with COGCC mechanical integrity testing rules.

Date: 01/10/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Prime Mover

1

Comment:

Gas motor

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Plumbed to surface

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 239892 Type: WELL API Number: 123-07680 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/29/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 1/10/22 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Fern Miller Wikstrand 2</p> <p>Company Name- KPK</p> <p>API- 05-123-07680</p> <p>In Weld County Colorado.</p> <p>While there, I observed PR well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Missing wellhead bolts were observed during inspection with signs of mechanical issues at time of inspection. Mechanical integrity of well may need to be tested to ensure mechanical integrity of wellbore, and wellhead equipment. Contact COGCC engineering. See picture 2.</p> <p>Comply with COGCC mechanical integrity testing rules. 1/10/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	01/10/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402922687	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5629693
699503438	Inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5629690