

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403049195

Date Received:
05/13/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>ATWATER BONNIE</u>	<u>432-755-0212</u>	<u>batwater@ogrisop.com</u>
<u>O'SHIELDS, CHARLIE</u>	<u>940-682-5030</u>	<u>coshields@ogrisop.com</u>
<u>WARD, GIENA</u>	<u>719-220-4041</u>	<u>gward@ogrisop.com</u>
<u>BACA DAVID</u>	<u>719-859-4066</u>	<u>dbaca@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690202807
Inspection Date: 04/21/2022 FIR Submit Date: 04/21/2022 FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC Company Number: 10758
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 308411

Location Name: APACHE CANYON-634S68W Number: 14NWNW County: LAS ANIMAS
Qtrqr: NWN Sec: 14 Twp: 34S Range: 68W Meridian: 6
W
Latitude: 37.087880 Longitude: -104.970570

FACILITY - API Number: 05-071-00 Facility ID: 271277

Facility Name: APACHE CANYON Number: 14-4
Qtrqr: NWN Sec: 14 Twp: 34S Range: 68W Meridian: 6
W
Latitude: 37.087880 Longitude: -104.970570

CORRECTIVE ACTIONS:

1 CA# 161189

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.

Date: 04/22/2022

Response: CA COMPLETED

Date of Completion: 05/10/2022

Operator Comment: MAINTENANCE HAS BEEN PERFORMED AND THE ENGINE SKID HAS BEEN CLEANED. THE IMPACTED SOIL AROUND THE SKID WAS CLEANED UP AND REMOVED FROM LOCATION AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED. THE LEAK ON THE PRODUCED WATER TANK HAS BEEN FIXED, ALL VALVES, PIPES, AND FITTINGS HAVE BEEN SECURELY FASTENED TO ENSURE GOOD MECHANICAL CONDITION.

COGCC Decision: Approved

COGCC Representative:

2 CA# 161190

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 04/27/2022

Response: CA COMPLETED

Date of Completion: 05/10/2022

Operator Comment: MAINTENANCE HAS BEEN PERFORMED AND THE ENGINE SKID HAS BEEN CLEANED. THE IMPACTED SOIL AROUND THE SKID WAS CLEANED UP AND REMOVED FROM LOCATION AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED. THE LEAK ON THE PRODUCED WATER TANK HAS BEEN FIXED, ALL VALVES, PIPES, AND FITTINGS HAVE BEEN SECURELY FASTENED TO ENSURE GOOD MECHANICAL CONDITION.

COGCC Decision: Approved

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA WARD

Signed: _____

Title: SR. ENVIRONMENTAL TECH.

Date: 5/13/2022 11:15:54 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403049195	FIR RESOLUTION SUBMITTED
403049205	PHOTO LOG

Total Attach: 2 Files