

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2022

Submitted Date:

06/01/2022

Document Number:

690202966

**FIELD INSPECTION FORM**Loc ID 481115 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10767

Name of Operator: TWIN BRIDGES RESOURCES LLC

Address: 475 17TH ST., STE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ROGOWSKI KELLY		krogowski@twinbridgesllc.com	
Kosola, Jason		jason.kosola@state.co.us	
WALLACE TOM		tcw@twinbridgesllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481334	WELL	DG	02/02/2022		071-09920	Red Rocks 1-13	RI

**General Comment:**

This is a Location Construction Inspection. The well was drilled as of 2/2/2022.  
See attached photos and additional details within this report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track existing access road.		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted at wellhead and entrance of location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 481334 CDP: \_\_\_\_\_

Comment: There was no form 42 Notice submitted for Construction. Operators will provide the Commission written notice 2 business days in advance of commencing construction or a major change at any Oil and Gas Location or Oil and Gas Facility. Operator did not comply with Rule 405.b.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
WADDLES	Yes		

Comments: Erosion BMPs: The straw wattles are not properly installed and do not protect down gradient runoff from disturbed areas.

Other BMPs: The silt fence is not properly installed or maintained.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/08/2022

2

Comment: There are multiple soil piles on location. Soil piles need to be properly marked and stored. Soil piles need to be protected and stabilized per Rule 1002.c.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Piles	Inadequate		
Comment	There are multiple piles on location which at least one pile may be drill cuttings. There has been no form 27 submitted for burial in a Cuttings Trench and there are piles sitting on the soil surface with inadequate stormwater protection.			
Corrective Action	Comply with 905.g. COGCC EPS staff (Jason Kosola) for directives.			Date: 06/02/2022

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): Comment: Pilot:  Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690202967	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5767693">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5767693</a>