

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

05/26/2022

Document Number:

701103146**FIELD INSPECTION FORM**Loc ID 315156 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL &amp; GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**General Comment:**

COGCC Follow Up Inspection Report Summary

Follow up to 05/23/2022 inspection # 701103142

Uncorrected action item

- Gas leaking from around pressure gauge on well.

Corrective action: Stop gas leak immediately

Corrective action date: 5/24/2022

See inspection 701103142 all other uncorrected actions items.

Communication:

Call made around 4 pm on 5/23/2022 from rest area off of Hwy 139.

Call was made to Lasso /31 Operating number on well sign. Answering service got a hold of Kris Freeman, Kris called me right back to say he would send his pumper to location to handle the leak.

Called made to Lasso answering service 5/25/2022 around 8:30 am to check on status of gas leak.

Received an email from Kris Freeman. "Levin was getting some more parts together yesterday. I'll find out if he was able to get the leak fixed and let you know."

**Location**Overall Good: ☐**Signs/Marker:**

Type			
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	Gas leaking from around pressure gauge on well.		
Corrective Action:	Stop gas leak immediately	Date:	05/24/2022

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Optical Gas Imaging Survey**

Survey Type: \_\_\_\_\_

Current Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Light Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: Partly Temperature: 68 (F)

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
3:30	PM	3:45	PM	Wellhead(s)

Comment: Gas leaking from around pressure gauge on well.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403060514	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763971">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763971</a>
701103148	Video and audio of gas leak from pressure gauge.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763968</a>
701103149	Leaking gauge on top of well (follow up 5/25/22)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763969">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763969</a>
701103151	Inspection 701103146 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763970">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763970</a>