

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2022

Submitted Date:

07/12/2022

Document Number:

699105700

FIELD INSPECTION FORM

Loc ID 459435 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459437	WELL	PR	12/13/2021	OW	123-48853	Becker D17-755	PR

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil in multiple spots needs to be removed. See attached photos.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	07/22/2022
Type	WEEDS		
Comment:	Weeds around well need to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	07/22/2022

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type		#	corrective date
Plunger Lift		# 1	
Comment:			
Corrective Action:			Date:
Bradenhead		# 1	
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
------	--	--	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 459437 Type: WELL API Number: 123-48853 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/16/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 7/11/22 at approximately 1043hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Becker D17-755 of Chevron, at API # 05-123-48853 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Weeds around well need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 7/22/22 Stained soil in multiple spots needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 7/22/22 See attached photo. Submit pictures on FIRR. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	07/12/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403101925	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800238
699105701	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800227