

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2022

Submitted Date:

07/20/2022

Document Number:

696304323**FIELD INSPECTION FORM**Loc ID 426631 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10773Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLCAddress: 5251 DTC PKWY STE 950City: GREENWOOD State: CO Zip: 80111**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
, CODY		ctrutt@fundareresources.com	PRINCIPAL AGENT
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Wolfe, Stephen		stephen.wolfe@state.co.us	
Linhardt, Cliff		clinhardt@fundareresources.com	DESIGNATED AGENT

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430492	WELL	PR	02/01/2021	OW	123-36168	Wildhorse 16-1613BH	PR

**General Comment:**

**Inspected Facilities**

Facility ID: 430492 Type: WELL API Number: 123-36168 Status: PR Insp. Status: PR

**Producing Well**

Comment: Work-Over Rig on Well. No Form 42 for Move-In, Rig-Up on File. Notice to Move-In, Rig-Up was not given in required time frame prior to commencement of Move-In, Rig-Up.

Corrective Action: Submit required notice as per Rule 405.e.

Date: 07/21/2022

**COGCC Comments**

Comment	User	Date
<p>On Wednesday 07/20/2022 at approximately 13:31 I, Inspector Erica Petrie, conducted a Field Inspection at Fundare Resources, Wildhorse 16-1613BH, Location #426631 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Work-Over Rig on Well. No Form 42 for Move-In, Rig-Up on File. Notice to Move-In, Rig-Up was not given in required time frame prior to commencement of Move-In, Rig-Up. Submit required notice as per Rule 405.e. Corrective Action Date 07.21.2022</p> <p>Spoke with Consultant on Location - He said Rig is on Well for Frac Prep and will be moving onto the Wildhorse 16-42 tomorrow at same point.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report</p>	petrie	07/20/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403111575	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5808481">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5808481</a>
696304324	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5808480">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5808480</a>