

FORM  
6Rev  
11/20

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

403064705

Date Received:

06/01/2022

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120

Contact Name: CANDICE BARBER

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Phone: (307) 233-4513

Address: P O BOX 173779

Fax:

City: DENVER State: CO Zip: 80217-

Email: CANDICE\_BARBER@OXY.COM

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-26912-00

Well Name: GRAY

Well Number: 18-16

Location: QtrQtr: SENW

Section: 16

Township: 4N

Range: 67W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number: 91-8125

Field Name: WATTENBERG

Field Number: 90750


### Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.314331

Longitude: -104.898474

GPS Data: GPS Quality Value: 1.6 Type of GPS Quality Value: PDOP Date of Measurement: 05/04/2022

Reason for Abandonment:


☐ Other

Casing to be pulled:



Estimated Depth:

Fish in Hole:



If yes, explain details below

Wellbore has Uncemented Casing leaks:



If yes, explain details below

Details:

### Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7358	7378	03/10/2022	B PLUG CEMENT TOP	7290

Total: 1 zone(s)

### Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	725	310	725	0	VISU
1ST	7+7/8	4+1/2	I-80	11.6	0	7524	675	7524	2700	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7290 with 2 sacks cmt on top. CIBP #2: Depth 6970 with 2 sacks cmt on top.  
CIBP #3: Depth 260 with 90 sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 90 sks cmt from 260 ft. to 15 ft. Plug Type: CASING Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at 4230 ft. with 100 sacks. Leave at least 100 ft. in casing 4162 CICR Depth  
Perforate and squeeze at 2800 ft. with 100 sacks. Leave at least 100 ft. in casing 2785 CICR Depth  
Perforate and squeeze at 2470 ft. with 170 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 120 sacks half in. half out surface casing from 825 ft. to 478 ft. Plug Tagged: ☒

Set 4 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: 840 ft. of 4+1/2 inch casing

Surface Plug Setting Date: 03/21/2022 Cut and Cap Date: 05/03/2022 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 43

\*Wireline Contractor: CUTTERS

\*Cementing Contractor: RANGER

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

CONTINUED PLUGGING PROCEDURE:

PERF AT 1700' WITH 185 SACKS OF CEMENT IN CASING, TAGGED TOC AT 950'

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: CANDICE BARBER

Title: REGULATORY ANALYST Date: 6/1/2022 Email: DJPOSTDRILL@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 8/17/2022

CONDITIONS OF APPROVAL, IF ANY:

### Condition of Approval

COA Type

Description

0 COA

### **Attachment List**

<b><u>Att Doc Num</u></b>	<b><u>Name</u></b>
403064705	FORM 6 SUBSEQUENT SUBMITTED
403064731	OPERATIONS SUMMARY
403064737	CEMENT BOND LOG
403064754	OTHER
403064777	OTHER
403064779	WIRELINE JOB SUMMARY
403064780	WELLBORE DIAGRAM
403064782	CEMENT JOB SUMMARY

Total Attach: 8 Files

### **General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Permit	2 months PA. Reviewed attachments. Pass.	08/16/2022

Total: 1 comment(s)