

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2022

Submitted Date:

10/05/2022

Document Number:

700704592**FIELD INSPECTION FORM**Loc ID 316580 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10384Name of Operator: GENESIS GAS & OIL COLORADO LLCAddress: 2441 NACOGDOCHES RD PMB 701City: SAN ANTONIO State: TX Zip: 78217**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Genesis	210-363-2859	mkimmel@genesiscoco.com	
, COGCC		dnr_cogccengineering@state.co.us	engineering
, COGCC		conor.pesicka@state.co.us	
Jeffrey Karcz	(303) 909-6401	jkarcz@genesiscoco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286505	WELL	AC	11/11/2008	OBW	103-10894	FLETCHER GULCH 3-21	TA

General Comment:**COGCC Inspection Report Summary**

On Tuesday 10/4/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at Genesis Fletcher Gulch 3-21, at Location # 316580 in Rio Blanco county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed well is not producing. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

During this inspection the following possible compliance issues were observed:

1. Location covered with weeds.
2. Well head signage is lacking information.
3. No emergency number posted.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Entrance		
Corrective Action:	Provide proper information on signage	Date:	11/16/2022

Emergency Contact Number:			
Comment:	No emergency number posted.		
Corrective Action:	Provide proper information on signage	Date:	11/16/2022

Good Housekeeping:			
Type	WEEDS		
Comment:	Location is covered in weeds		
Corrective Action:	Remove weeds	Date:	10/14/2022

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Well head		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 286505 Type: WELL API Number: 103-10894 Status: AC Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last Mit done 6/30/2015
Well was found in state of Temporary Abandonment.

Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.

Date: 11/16/2022**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403190020	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880097
700704599	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880089