

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2022

Submitted Date:

10/07/2022

Document Number:

699106132**FIELD INSPECTION FORM**Loc ID 434121 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434121	LOCATION	AC	01/01/2022		-	Helton 5-63-27	AC

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment in multiple locations needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/14/2022
Type	TRASH		
Comment:	Trash in multiple locations needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/14/2022
Type	OTHER		
Comment:	Oily Waste in load-out box by electrical box needs removed. See attached photos.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	10/14/2022
Type	UNUSED EQUIPMENT		
Comment:	Chemical Totes are not being used they need to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/14/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER						
Comment:	Chemical Totes					
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Inadequate	Walls Insufficient		Inadequate
Comment:	Berm around Chemical tanks needs to be repaired. See attached photos.			

Corrective Action:					Repair or other secondary containment devices per Rule 912.d.(1).		Date:		10/14/2022	
Contents		#	Capacity	Type	Tank ID	SE GPS				
OTHER		1	500 BBLs	STEEL AST		40.370200,-104.427500				
Comment:					Frac Tank					
Corrective Action:					Date:					
<u>Paint</u>										
Condition										
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance						
Other	Inadequate	Walls Insufficient	Base Sufficient	Inadequate						
Comment:					Berm around Frac tank needs to be repaired. See attached photos.					
Corrective Action:					Repair or other secondary containment devices per Rule 912.d.(1).		Date:		10/14/2022	
<u>Venting:</u>										
Yes/No	NO									
Comment:										
Corrective Action:										Date:
<u>Flaring:</u>										
Type										
Comment:										
Corrective Action:										Date:

Inspected FacilitiesFacility ID: 434121 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 10/5/22 at approximately 1014hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Helton 5-63-27 of Civitas, at Location ID: 434121 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Equipment in multiple locations needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 10/14/22.</p> <p>Trash in multiple locations needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 10/14/22.</p> <p>Chemical Totes are not being used they need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 10/14/22.</p> <p>Berm around Frac tank needs to be repaired. Repair or other secondary containment devices per Rule 912.d.(1). With a corrective action date of 10/14/22.</p> <p>Berm around Chemical tanks needs to be repaired. Repair or other secondary containment devices per Rule 912.d.(1). With a corrective action date of 10/14/22.</p> <p>Oily Waste in load-out box by electrical box needs removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 10/14/22.</p> <p>See attached photo.</p> <p>Submit pictures on FIRR.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	10/07/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403190884	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880954
699106133	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880940