

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403200441

Date Received:

10/18/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203989

Inspection Date: 08/15/2022

FIR Submit Date: 08/19/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334765

Location Name: Federal Number: PA 23-12 County: _____

Qtrqr: NESW Sec: 12 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.452105 Longitude: -107.949802

FACILITY - API Number: 05-045- -00 Facility ID: 334765

Facility Name: Federal Number: PA 23-12

Qtrqr: NESW Sec: 12 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.452105 Longitude: -107.949802

CORRECTIVE ACTIONS:

2 ☒ CA# 163988

Corrective Action: Comply with 1002.f and implmenet BMPs in accordance with good engineering practices to allow for proper stormwater discharge from the Location

Date: 08/26/2022

Response: CA COMPLETED

Date of Completion: 08/22/2022

Operator Comment: The storm water BMPs / issues noted in the inspection reporter were cleaned out and repaired. This corrective action is complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.
-----------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment: The storm water BMPs / issues noted in the inspection reporter were cleaned out and repaired. This corrective action is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 10/18/2022 10:43:28 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403200441	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files