

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2022

Submitted Date:

11/21/2022

Document Number:

699805245

FIELD INSPECTION FORMLoc ID 334901 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270069	WELL	PR	09/07/2004	GW	045-09447	SHIDELER 32-2D (G32NEC)	PR
270070	WELL	PR	04/01/2013	GW	045-09446	SHIDELER 32-8C (G32NEC)	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 11/18/22 at approximately 14:00 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at CAERUS PICEANCE LLC SHIDELER-66S92W /32SWNE.
Location #334901 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Flow line heating insulation open ended and not capped with a corrective action date of 11/28/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Flow line heating insulation open ended and not capped.		
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.	Date:	11/28/2022

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 270069 Type: WELL API Number: 045-09447 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 270070 Type: WELL API Number: 045-09446 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Check Dams				
Ditches						
		Sediment Traps				
		Gravel				
		Berms				
Gravel						
		Culverts				
Sediment Traps						
Compaction						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Equipment for corrective actions	depaoloc	11/21/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403235802	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5921444
699805246	Photos for Insp. #699805245	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5921437