

Location					
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					Date:
Corrective Action:					Date: _____
Good Housekeeping:					
Type	UNUSED EQUIPMENT				
Comment:	Unused wellhead fencing, see attached photo.				
Corrective Action:	Comply with Rule 606				Date: <u>12/30/2022</u>
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
					corrective date
Type: Other	# 1				
Comment:	Master valve is leaking with stained soil below, see attached photo.				
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.				Date: <u>12/30/2022</u>
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:
Type: Flow Line	# 1				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:	Bradenhead valve is exposed at surface.				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Tank battery #448358				
Corrective Action:					Date:

Paint				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 275911 Type: WELL API Number: 123-22698 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/20/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 12/2/2022 at approximately 09:30 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the KPK Bernhardt 7-16 API #123-22698 in Weld County, Colorado.</p> <p>While there, I observed unused equipment on location and that the wellhead master valve was leaking with stained soil around the wellhead. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 12/30/2022, Rule 608.e. with a corrective action date of 12/30/2022. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	12/02/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403247919	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5931125
697006797	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5931121