

Document Number:
403202360

Date Received:
10/19/2022

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: CANDICE BARBER
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (307) 233-4513
 Address: P O BOX 173779 Fax: _____
 City: DENVER State: CO Zip: 80217- Email: CANDICE_BARBER@OXY.COM

For "Intent" 24 hour notice required, Name: Revas, Robbie Tel: (720) 661-7242
 Email: robbie.revas@state.co.us

COGCC contact: _____

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-123-20375-00
 Well Name: HSR-TEETS Well Number: 5-29A
 Location: QtrQtr: SWNW Section: 29 Township: 2N Range: 67W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.110693 Longitude: -104.921675
 GPS Data: GPS Quality Value: 2.1 Type of GPS Quality Value: PDOP Date of Measurement: 10/06/2022

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7664	7684	08/01/2022	B PLUG CEMENT TOP	7322
NIOBRARA	7374	7546	08/01/2022	B PLUG CEMENT TOP	7322
J SAND	8084	8102	08/01/2022	B PLUG CEMENT TOP	8000

Total: 3 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	819	575	819	0	VISU
1ST	7+7/8	4+1/2	I-80	11.6	0	8216	215	8216	7050	CBL
S.C. 1.1						5281	235	5283	4280	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 8000 with 2 sacks cmt on top. CIBP #2: Depth 7322 with 2 sacks cmt on top.
 CIBP #3: Depth 260 with 90 sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 4260 ft. with 185 sacks. Leave at least 100 ft. in casing 3780 CICR Depth
 Perforate and squeeze at 2800 ft. with 220 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at 1800 ft. with 220 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 (Cast Iron Cement Retainer Depth)

Set 120 sacks half in. half out surface casing from 920 ft. to 565 ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 920 ft. of 4+1/2 inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: 56
 Surface Plug Setting Date: 08/08/2022 Cut and Cap Date: 10/03/2022

*Wireline Contractor: RANGER *Cementing Contractor: RANGER

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: CANDICE BARBER
 Title: REGULATORY ANALYST Date: 10/19/2022 Email: DJPOSTDRILL@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 1/24/2023

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description
0 COA	

Attachment List

Att Doc Num	Name
403202360	FORM 6 SUBSEQUENT SUBMITTED
403202372	OPERATIONS SUMMARY
403202385	CEMENT BOND LOG
403202387	CEMENT BOND LOG
403202388	WIRELINE JOB SUMMARY
403202389	WELLBORE DIAGRAM
403202392	CEMENT JOB SUMMARY
403202397	OTHER

Total Attach: 8 Files

General Comments

User Group	Comment	Comment Date
Permit	Reviewed attachments. Pass.	12/12/2022

Total: 1 comment(s)