

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type			
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
Produced Water	WELLHEAD		
Comment:	There was a produced water spill at the wellhead which flowed off the southwest and northwest side of the location. There are signs that the produced water flowed approximately 650 ft. from the wellsite down and along CR 31.9. Operator was immediately notified and a spill report has been submitted.		
Corrective Action:	Investigate, document, and clean up per Rule 912.a.		Date: 03/22/2023

In Containment:	No		
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403327330	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6029581
690203911	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6029574