

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403355305

Date Received:
03/24/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Smith, Sydney

Phone

303-910-4511

Email

ssmith@fundareresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 694100034

Inspection Date: 12/07/2022

FIR Submit Date: 12/15/2022

FIR Status: _____

Inspected Operator Information:

Company Name: FUNDARE RESOURCES OPERATING COMPANY LLC

Company Number: 10773

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqtr: NENW Sec: 4 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.785820 Longitude: -103.985890

FACILITY - API Number: 05-123-00 Facility ID: 483043

Facility Name: Wildhorse 04-0424H Number: _____

Qtrqtr: NENW Sec: 4 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.785820 Longitude: -103.985890

CORRECTIVE ACTIONS:

1 CA# 166615

Corrective Action: repair and maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. the site was not attended at the time of the inspection.

Date: 12/22/2022

Response: CA COMPLETED

Date of Completion: 12/15/2022

Operator Comment: Fencing Properly Installed Around Open Excavation in Accordance with Rule 913.b(5)B.i. Please See Attached Photos.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 166616

Corrective Action: Lack of maintenance/good housekeeping procedures - see above statement (see photos). Comply with Rules 606 and 1002.f.(2).D.

Date: 12/22/2022

Response: CA COMPLETED

Date of Completion: 12/19/2022

Operator Comment: Maintenance & Good Housekeeping Procedures Implemented to Bring Location Within Compliance of Rules 606 and 1002.f.(2).D. Please See Attached Photos.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 166617

Corrective Action: Install sign to comply with Rule 210.e.

Date: 12/22/2022

Response: CA COMPLETED

Date of Completion: 12/12/2022

Operator Comment: Signage Properly Labeled & Installed at Location Entrance in Accordance with Rule 210.e. Please See Attached Photos.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 166618

Corrective Action: Install new BMPs in accordance with 1002.f.(2) to prevent runoff and completely contain impacts along access road

Date: 12/22/2022

Response: CA COMPLETED

Date of Completion: 12/20/2022

Operator Comment: Access Roadside Diversion Ditch Redefined & BMPs Re-Installed in accordance with 1002.f.(2) Please See Attached Photos.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Melissa Parrish

Signed: _____

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403355336	Wildhorse 04-0424H COGCC Corrective Actions Completed
-----------	---

Total Attach: 1 Files