

Gils Hot Oil service  
State 12-2  
Location # 324674



location



Tank battery lacking signage

**Gils Hot Oil service  
State 12-2  
Location # 324674**



**Tank battery lacking signage**



**location and weeds**



**Gils Hot Oil service  
State 12-2  
Location # 324674**



**Insufficient secondary containment and weeds**



**Insufficient secondary containment and weeds**

**Gils Hot Oil service  
State 12-2  
Location # 324674**



**Insufficient secondary containment and weeds**



**Well signage lacking information**

Gils Hot Oil service  
State 12-2  
Location # 324674



No Braden head access



Debris

**Gils Hot Oil service  
State 12-2  
Location # 324674**



**Well head and debris**



**Access road needs maintained**

**Gils Hot Oil service  
State 12-2  
Location # 324674**



**Access road needs maintained**



**Access road needs maintained**

**Gils Hot Oil service  
State 12-2  
Location # 324674**



**Access road needs maintained**

