

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2023

Submitted Date:

07/20/2023

Document Number:

699504876

FIELD INSPECTION FORMLoc ID 318295 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241052	WELL	PR	03/20/1995	OW	123-08840	ROCKY MOUNTAIN FUEL B 3	PR

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	weeds unmanaged on lease road and location		
Corrective Action:	Comply with rule 606	Date:	07/27/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused pumpjack on location needs to be removed.		
Corrective Action:	Comply with rule 606	Date:	08/20/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric / automation		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241052 Type: WELL API Number: 123-08840 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/11/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On 7/20/23 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Rocky Mountain Fuel B 3</p> <p>Company Name- KPK</p> <p>API- 05-123-318295</p> <p>In Weld County Colorado.</p> <p>While there, I observed PR well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds. Rule 606. 7/27/23</p> <p>Unused equipment. Rule 606. 8/20/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This inspection does not nullify any orders or corrective actions from the ECMC.</p> <p>This is a summary of inspection report.</p>	medinaj	07/20/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403473699	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6192384
699504877	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6192378