

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403534723

Date Received:

09/19/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708300817

Inspection Date: 08/22/2023

FIR Submit Date: 09/05/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 334871

Location Name: WILLIAMS-67S96W Number: 1NWNW County: GARFIELD

Qtrqr: NWN Sec: 1 Twp: 7S Range: 96W Meridian: 6  
W

Latitude: 39.472099 Longitude: -108.064895

### FACILITY - API Number: 05-045- -00 Facility ID: 211511

Facility Name: UNOCAL Number: GM 11-1

Qtrqr: NWN Sec: 1 Twp: 7S Range: 96W Meridian: 6  
W

Latitude: 39.472099 Longitude: -108.064895

### CORRECTIVE ACTIONS:

1 ☒ CA# 180221

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 07/06/2023

Response: CA COMPLETED

Date of Completion: 08/22/2023

Operator Comment: This pad needs nothing more done. The rilling has been fixed but sediment onto pad is handled by on pad BMP's which are sufficient. BMPs are maintained as needed. CA has been addressed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: This pad needs nothing more done. The rilling has been fixed but sediment onto pad is handled by on pad BMP's which are sufficient. BMPs are maintained as needed. CA has been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 9/19/2023 11:44:59 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403534723	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files