

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2023

Submitted Date:

09/08/2023

Document Number:

708200541

### FIELD INSPECTION FORM

Loc ID 313960 Inspector Name: Edwardson, Dylan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 98220  
Name of Operator: YOUNG GAS STORAGE COMPANY LTD  
Address: P O BOX 1087  
City: COLORADO SPGS State: CO Zip: 80944

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
6 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TRINKO, ANTHONY		anthony_trinko@kindermorgan.com	
		logan.hansen@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272062	WELL	AC	04/28/2004	STOW	087-08133	YOUNG 45	RI
313960	LOCATION	AC			-	YOUNG-64N58W 11NENE	RI

**General Comment:**

This is an Interim Reclamation and Stormwater Inspection for Well API #087-08133.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Concrete structures observed on the south end of location.		
Corrective Action:	Comply with Rule 606 and remove any unused equipment. Location will remain out of compliance until the corrective action has been resolved.	Date:	09/05/2023
Type	DEBRIS		
Comment:	Bullet casings observed on the eastern portion of location.		
Corrective Action:	Comply with Rule 606 and remove debris. Location will remain out of compliance until the corrective action has been resolved.	Date:	09/05/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Other	#		corrective date
Comment:	NFPA Placards on day tank and equipment are either missing, not legible, or peeling/faded/cracked. Refer to attached inspection photos for additional.		
Corrective Action:	Install sign to comply with Rule 605.g. Location will remain out of compliance until the corrective action has been resolved.	Date:	09/05/2023
Type: Other	#		
Comment:	No wildlife protection device (e.g. netting) observed around secondary containment at day tank. Refer to attached inspection photos.		
Corrective Action:	Install or repair wildlife protection equipment per Rule 902.b. Location will remain out of compliance until the corrective action has been resolved.	Date:	09/05/2023

**Venting:**

Yes/No		
Comment:	<input type="text"/>	
Corrective Action:		Date:

**Flaring:**

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 272062 Type: WELL API Number: 087-08133 Status: AC Insp. Status: RI

Facility ID: 313960 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Fail Production areas stabilized ? Fail  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? F

Comment This location does not comply with Rule 1003. During this inspection, Staff observed that the interim areas do not appear to be progressing Rule 1003 standards and regulations. The interim areas are predominantly undesirable vegetation (e.g. russian thistle and kochia; and Colorado List B Noxious Weed- Scotch Thistle) was observed to be growing throughout and does not appear to have been recently managed. Additional reclamation activities are required. Refer to attached inspection photos.

Corrective Action Comply with Rule 1003. Location will remain out of compliance until the corrective action has been resolved.

Date 09/05/2023

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:  Date:

Overall Final Reclamation  Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. During this inspection, Staff observed that portions of the access road are experiencing erosion degradation with evidence of rilling. Additionally, no apparent stormwater control measures were observed to control and/or contain sediment from leaving location due to rill eorsion occuring on the access road. Refer to attached inspection photos.

Corrective Action: Comply with Rule 1002.f. Location will remain out of compliance until the corrective action has been resolved. Date: 09/05/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403524992	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6246124">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6246124</a>
708200555	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6246112">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6246112</a>