

OIL AND GAS CONSERVATION COMMISSION  
OF THE  
STATE OF COLORADO  
ROOM 312, STATE SERVICES BLDG.  
1525 SHERMAN ST.  
DENVER 3, COLORADO



00053470

January 31, 1964

United States Development Corp.  
434 South Main  
Salt Lake City, Utah 84100

*P.O. says  
"unknown  
not in directory"*

Gentlemen:

We have contacted you several times in the past relative to the status of the Banker-Robinson Ranch #1 well, Lot 10, Section 12, Township 1 North, Range 103 West, Rio Blanco County, Colorado.

We should like very much to have you advise us of the status of this well, as well as your future plans for operation. Besides the fact that several times in the past the bonding company has asked us for cancellation of the bond, one of our rules provides that completion reports be filed within 30 days after the completion of any well - completion meaning either the running of pipe preparatory to producing, or plugging. Maximum penalty for violation of our rules and regulations is \$1000 per violation and \$1000 per day while in violation.

We solicit your prompt cooperation in this matter, and shall anticipate an answer from you at an early date.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

William R. Smith, Deputy Director

WRS:cm

cc: United States Development Corp.  
817 Newhouse Bldg., Salt Lake City, Utah

*Unknown here -  
P.O. returned*

*will file*

December 16, 1965

Fireman's Fund Insurance Company  
641 East South Temple  
Salt Lake City, Utah 84102

Re: U.S. Development Corporation  
Bond # L-6058176-\$2500  
# 1 Banker- Lot 10 12-1N-103 W  
Rio Blanco County, Colorado

Gentlemen:

The above bond may be cancelled as of December 8, 1965.

Very truly yours,  
Oil and Gas Conservation Commission

D.V. Rogers, Director

Doucette  
Enc: Bond  
CC: U.S. Development Corporation

*Alouette ✓*



The **FUND**  
Insurance Companies

FIREMAN'S FUND INSURANCE COMPANY • HOME FIRE & MARINE INSURANCE COMPANY • NATIONAL SURETY CORPORATION  
641 EAST SOUTH TEMPLE • SALT LAKE CITY 2, UTAH • DAvis 2-1355

RECEIVED  
SEP 22 1961  
OIL & GAS  
CONSERVATION COMMISSION

Salt Lake City Office

September 20, 1961

12-1N-10300

Oil & Gas Conservation Commission  
Room 312 - State Services Building  
Denver 3, Colorado

Re: Bond No. L 6058176  
United States Development Corp.  
Robinson well - \$2500.00

Gentlemen:

Once again we would appreciate your advice as to whether or not the above captioned bond can be released. In your letter to us of June 27, 1961, you stated that required data on the well had not yet been filed.

If you are unable to release us of liability under this bond, would you please let us know just what the insured has left to complete in order to bring this to a close.

Thank you for your help in this matter.

Cordially,

  
Pat Van Derck  
Bond Underwriter

pv

AJJ	
DVR	
WRS	
HHM	
JAM	
FJP	
JJD	
FILE	

*well file*

June 27, 1961

Fireman's Fund Insurance Company  
641 East South Temple  
Salt Lake City 2, Utah

*12-1A-1031J*

Re: Bond No. L 6058176  
United States Development Corp.  
Robinson well-\$2500.

Gentlemen:

In answer to your letter of June 26 regarding the above bond cancellation, wish to advise bond cannot be released as the required data on well ~~has~~ not been filed.

Very truly yours,  
OIL AND GAS CONSERVATION COMMISSION  

---

A.J.Jersin, Director

LD




The  
**FUND**  
Insurance Companies

Salt Lake City Office

FIREMAN'S FUND INSURANCE COMPANY • HOME FIRE & MARINE INSURANCE COMPANY • NATIONAL SURETY CORPORATION

641 EAST SOUTH TEMPLE • SALT LAKE CITY 2, UTAH • DAVIS 2-1355

June 26, 1961



Oil & Gas Conservation Commission  
Room 312 - State Services Building  
Denver 3, Colorado

OIL & GAS  
CONSERVATION COMMISSION


Re: Bond No. L 6058176  
United States Development Corp.  
(Robinson Well, Rio Blanco County)  
\$2500 Oil & Gas Drilling Bond

Gentlemen:

The above captioned bond has been executed by us in the amount of \$2500.00, effective June 8, 1960.

We would very much appreciate receiving your advice on this bond as to whether or not we may receive your confirmation of cancellation. Our insured cannot be contacted nor do we seem to be able to obtain his continuation premium for the bond and we would therefore like to be relieved of our liability.

Cordially,

  
Pat Van Derck  
Bond Underwriter

pv

**United States**  
**Uranium Development Corp.**

434 South Main  
Salt Lake City, Utah



Oil and Gas Conservation Commission  
Room 312 State Services Bldg  
1525 Sherman Road  
Denver  
Colo

*Mace*

*All right that was  
43*

*Sent back requires  
without a note*

**OIL AND GAS CONSERVATION COMMISSION**

**OF THE  
STATE OF COLORADO  
STEVE McNICHOLS, GOVERNOR  
ROOM 312, STATE SERVICES BLDG.  
1525 SHERMAN ST.  
DENVER 3, COLORADO**

**WARWICK M. DOWNING  
CHAIRMAN  
H. C. BRETSCHNEIDER  
VICE-CHAIRMAN  
W. A. DILLON  
HARVEY H. HOUSTON  
CHARLES D. CONRADO  
A. J. JERSIN  
DIRECTOR**

May 19, 1961,

1st

U.S. Development Corporation  
817 Newhouse Building  
Salt Lake, Utah

Gentlemen:

Present status of well.

A review of our files indicates that we have not received reports, as checked below, for the following well:


# 1 Banker- Robinson Ranch 12-1N-103 W Rangely, Rio Blanco

- Form 2 - Notice of Intention to Drill
- Form 4 - Sundry Notices and Reports on Wells
- Form 5 - Well Completion Report
- Form 6 - Plugging Record
- Form 10 - Certificate of Clearance
- Others -

In order to comply with the Rules and Regulations of the Oil and Gas Conservation Commission, it is necessary that you submit the above requested reports to this office as soon as possible.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

  
A. J. Jersin, Director

AJJ:cm