

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/13/2023

Submitted Date:

11/13/2023

Document Number:

699107798

FIELD INSPECTION FORM
 Loc ID 447608 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447609	TANK BATTERY	AC	09/08/2016		-	BOCKIUS 15-1,8, PFANNEBECKER C14-32 D,C15-22	SI

General Comment:[Inspection on the tank battery](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment around the location needs to be removed for good housekeeping		
Corrective Action:	Comply with Rule 606	Date:	11/27/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Unmarked risers in multiple spots need to be marked by identifying what they are and tagged with OOSLAT. See attached photos		
Corrective Action:	Comply with the 1100 rules.		Date: 11/27/2023
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	OTHER	BV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	53 BBLs				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					
Date:					

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLs	STEEL AST		40.312700,-104.527400	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
Date:			

Flaring:

Type			
Comment:			
Corrective Action:			
Date:			

Inspected FacilitiesFacility ID: 447609 Type: TANK API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment

ECMC Inspection Report Summary
 On Monday 11/13/23 at approximately 0815hrs I, Inspector Adam Burns,
 Conducted an on-site inspection at Bockius 15-8, 8, Pfannebecker C14-32, C15-22 Tank
 Battery of Chevron.
 Location ID #447609 in Weld County, Colorado.
 During this inspection the following possible compliance issues were observed:
 Unused Equipment around the location needs to be removed for good housekeeping.
 Comply with Rule 606. With a Corrective Action date of 11/27/23
 Unmarked risers in multiple spots need to be marked by identifying what they are and
 tagged with OOSLAT. Comply with the 1100 rules. With a Corrective Action date of
 11/27/23
 A follow up on this site inspection needs to be conducted to ensure the
 compliance issues have been corrected to comply with ECMC rules.
 This is a summary of the inspection report.

User

burnsa

Date

11/13/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403593506	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6320142
699107799	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6320124