

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Contaminated soil by wellhead needs to be removed		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e	Date:	04/06/2024
Type	OTHER		
Comment:	wellhead sign is covered by electric equipment and cannot read. Sign needs to be placed in a visible area.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/06/2024
Type	OTHER		
Comment:	mechanical issue on wellhead, small leak was observed during inspection see pic 3		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	04/06/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240401 Type: WELL API Number: 123-08189 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 3/22/24 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- State 9 Company Name- KPK API- 05-123-08189 In Weld County Colorado. While there, I observed PR well During this inspection the following possible compliance issues were observed: Mechanical issue. Rule 608.e. 4/6/24 Contaminated soil. Rule 908.e. 4/6/24 Wellhead sign not visible. Rule 605.e. 4/6/24 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	03/22/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403736540	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6487141
699505643	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6487129