

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2024

Submitted Date:

03/29/2024

Document Number:

713600882

## FIELD INSPECTION FORM

Loc ID 321621 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 17180

Name of Operator: CITATION OIL &amp; GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
GONCALVES STEFFY		sgoncalves@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207544	WELL	PR	11/05/1984	OW	017-06479	RHOADES 22-35 2	RI

**General Comment:**

This is a location inspection of the RHOADES 22-35 #2 wellsite.  
See attached photos and additional details within this report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	There is an area where vehicles are driving outside of the access road boundary causing unnecessary disturbance that will need to be reclaimed. Repeated or flagrant instance(s) of failure to restrict lease access to lease roads which result in unreasonable land damage or crop losses shall be subject to a penalty under Rule 523.		
Corrective Action:	Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e rule.	Date:	03/29/2024

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	The well sign is faded and not legible.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/30/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	There is metal panels laying on the ground not in use. All unused equipment or supplies need to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	04/15/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	Pump Jack		
Comment:	There is oil leaking out of the pumpjack engines that must be controlled and cleaned up.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.		Date: 03/29/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: There are fuel/oil/chemical barels with no secondary containment.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 04/05/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403736443	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6487001">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6487001</a>
713600883	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6486999">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6486999</a>