



02054683



State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

RECEIVED

NOV 14 2010

COGCC

LOSS OF WELL CONTROL REPORT

As required by Rule 327.

Report taken by:

DAVE ANDREWS

1. OGCC Operator Number: 100185
 2. Name of Operator: EnCana Oil & Gas
 3. Address: 370 17th Street
 City: Denver State: CO Zip: 80202

4. Contact Name & Phone
 Gage Soehner
 Ph: 720-951-0732
 Fax:

WELL LOCATION INFORMATION

5. API Number: 05-045-19511-00
 6. County: Garfield
 7. Well Name: Twin Creek
 8. Well Number: 1-9C1
 9. Unit Name (if appl.): Hunter Mesa
 10. Unit No: COC55972E
 11. QtrQtr: SWSE Sec: 1 Twp: 7S Rng: 92W Meridian: 6
 12. Footage From Exterior Section Lines: 844 FSL 1834 FEL
 13. Field Name: Mamm Creek
 14. Field Number: 52500

CASING INFORMATION

15. Surface Casing Size: 9 5 / 8 Weight per Foot: 36 Grade: J55 True Vertical Setting Depth: 1102
 16. Intermed. Casing Size: / Weight per Foot: Grade: True Vertical Setting Depth:

KICK INFORMATION

17. True Vertical Depth at Kick: 4110'
 18. Formation at Kick: Williams Fork
 19. Formation Code: WMFK
 20. Shut-in Drill Pipe Pressure (SIDPP): 140 psi.
 21. Shut-in Casing Pressure (SICP): 52 psi.
 22. Mud Weight at Time of Kick: 10.4 ppg.
 23. Pit Gain: 15 bbls.
 24. Time and Date Shut In: 7:56 AM 11/13/10
 25. Mud Weight Required to Control Well: 11.1 ppg
 26. Type of Kick: ☒ Gas ☐ Oil ☐ Water
 27. Comments (describe actions to control in detail): Well was shut in while drilling at 4,349' MD & 4,110' TVD. Pressures were recorded and lost circulation material was added to system until a level of 17% LCM was reached while building mud weight to an 11.1 ppg. Kill mud was started pumping at 9:30 AM at 40 strokes per minute. At 11:00 am flare was dead after first bottoms up circulation. Flow check was taken and there was no flow. The rig went off of the choke and resumed drilling.