

Status	Receipt	Permit	TWN	RNG	SEC	Q160	Q40	UTM_x	UTM_y	Use	Contact/Sample Attempts	Full Name
Wrong Location	28501	96266-VE	1.0 N	67.0 W	7 NE	NE		506290.5	4435628.8	Domestic	Verbal approval for Permit #6345--A, which is actually located in T9S R47W. Sent access request letter 10/2/18.	BALDWIN, LOWELL
Landowner Declined	9065243	70923-	1.0 N	67.0 W	7 NW	NE		505431	4435807.5	Domestic	Received postcard 10/16/18, landowner declined sampling.	LANDWEHR, PAUL
Eliminated - Use	21906	21906-MH	1.0 N	67.0 W	6 SW	SW		505109.7	4436060.3	Monitoring/Sampling	-	MARTIN EXPLORATION MANAGEMENT CO
Eliminated - Use	24875	24875-MH	1.0 N	67.0 W	6 SW	SW		505109.7	4436060.3	Monitoring/Sampling	-	MARTIN EXPLORATION MGMT CO
Well no longer exists	9060178	9501-	1.0 N	67.0 W	5 SW	SW		506682.1	4436042.8	Domestic	Attempted to sample 11/8/18. Searched area and did not find water well. Confirmed with landowner they are not aware a well exists.	MILLER & JOHNSON FARMS