

Federal 6204
Api # 05-045-06792
Inspection # 689702076



Battery sign.

Federal 6204
Api # 05-045-06792
Inspection # 689702076



Location photo.

Federal 6204
Api # 05-045-06792
Inspection # 689702076



Unmarked risers at separator.

Federal 6204
Api # 05-045-06792
Inspection # 689702076



Deadman marker is broke off. Unmarked risers at separator.

Federal 6204
Api # 05-045-06792
Inspection # 689702076



Unmarked risers



Unmarked riser open ended.

Federal 6204
Api # 05-045-06792
Inspection # 689702076



No gate at tank.