

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2019

Submitted Date:

06/06/2019

Document Number:

679704383**FIELD INSPECTION FORM**Loc ID 420981 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Sanford, Anita		atlx@chevron.com	
Peterson, Diane	970-675-3842	dlpe@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421489	WELL	PR	08/19/2011	OW	103-11855	EMERALD 94X	PR
421610	WELL	PR	02/01/2018	OW	103-11858	EMERALD 93X	PR

**General Comment:**[COGCC Inspection Report Summary.](#)

On 6-6-2019 at approximately 16:15, inspector Rick Moran, conducted a routine well inspection at Chevron's well Emerald 93X & 94X in Rio Blanco county.

During this inspection the following compliance issues were observed:

1) Well head sign missing emergency contact number & 911. Photos 2 & 3. Complete by 7-8-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704383.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Both well head signs are missing the operator emergency phone number "911". The emergency phone is present on the entrance to the lease road.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	07/08/2019

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>				corrective date
Type: Submersible Pump	# 2			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 421489 Type: WELL API Number: 103-11855 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

Facility ID: 421610 Type: WELL API Number: 103-11858 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704384	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4842867">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4842867</a>