

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402069713

Date Received:

06/10/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 35080

Name of Operator: GRAND MESA OPERATING CO

Address: 1700 N. WATERFRONT PKWY BL 600

City: WICHITA State: KS Zip: 67206

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Michael Reilly

316-265-3000

mreilly@gmocks.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900470

Inspection Date: 03/11/2019

FIR Submit Date: 03/13/2019

FIR Status: _____

Inspected Operator Information:

Company Name: GRAND MESA OPERATING CO

Company Number: 35080

Address: 1700 N. WATERFRONT PKWY BL 600

City: WICHITA State: KS Zip: 67206

LOCATION - Location ID: 449468

Location Name: PIKES Number: 1-14 County: CROWLEY

Qtrqtr: SWNE Sec: 14 Twp: 20S Range: 56W Meridian: 6

Latitude: 38.316090 Longitude: -103.635830

FACILITY - API Number: 05-025-00 Facility ID: 449472

Facility Name: PIKES Number: 1-14

Qtrqtr: SWNE Sec: 14 Twp: 20S Range: 56W Meridian: 6

Latitude: 38.316090 Longitude: -103.635830

CORRECTIVE ACTIONS:

1 ☒ CA# 123212

Corrective Action: Seed and stabilize the disturbed soils. Comply with 1004 Rules

Date: 04/24/2019

Response: CA COMPLETED

Date of Completion: 04/13/2019

Operator Comment: Location and road ripped, graded, seeded, straw and crimped. Waiting on the Colorado SLB as to if the road reclamation is sufficient or if they want more work completed. SLB responded that they want the yellow, green & pink portions of the access road left undisturbed and red portion seeded and reclaimed. Red portion seeded and wellsite seeded. Wait on 80% reclamation

COGCC Decision: Approved pending re-inspection

COGCC Representative: Access road from CO Rd. 38 running north and south toward the location will need to be reclaimed. The preexisting road from CO Rd. 34 running east west can remain (highlighted yellow, green, and pink).

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Reilly

Signed: _____

Title: President

Date: 6/10/2019 2:47:00 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402069713	FIR RESOLUTION SUBMITTED
402069748	SLB E-mail regarding road reclamation

Total Attach: 2 Files